

Index: Mechanical Tolerance Stackup and Analysis

Bryan R. Fischer

Accuracy and precision			8-9
Advanced Dimensional Management			14, 21, 78, 118, 208, 251, 286, 329-366
Ambiguity			4, 8-14
ASME B89			48
ASME Y14.5M-1994			5, 19, 22, 23, 54, 181, 187, 188, 207, 226, 271, 384
	fundamental rules		54
	rule #1		5
	simultaneous requirements and		187, 188
Assembly shift			49, 68-74, 87-90, 93, 96-99, 102-103, 288, 293-296, 303-327, 378-383, 388
	calculations		70-71
		fastener diameters used in	70
	chain of dimensions and tolerances and		70, 99-104
	clearance and		68-69
	definition of		68
	dimension values and		70
	direction of		70, 288, 293-296
		labeling in the tolerance stackup	70
	directional bias in		68
	effect of assembly forces on		68, 303
		effect of gravity	68, 87-90, 127-129, 378-383
	effect of assembly process on		68-73, 233-234, 378-383, 388
		adds to total predicted variation	68
		default condition in this text	73
		options for including in tolerance stackup	72-74
		reduces total predicted variation	72
	effect of mating features on		68
		features of size	68
		threaded fasteners	71-72, 74
	fixed-fastener calculations and		70-72, 74, 161-164, 167, 168, 228
	floating-fastener calculations and		70, 73, 100, 161-164, 167, 168, 228
	including in the tolerance stackup		70, 73-74
	rotational assembly shift		303-304, 304-327
		formulas and calculations	313, 315, 323-324, 326
		reporting in a tolerance stackup report	309, 311, 316, 322, 323, 327
	rules for		74-75
	sources of		68
	worst-case		69-70
Assumptions			74-78, 99, 120, 393
	default conditions in this text		77-78, 99
		specified temperature(s)	77
		static state	77
	framing the problem		77-78, 99, 393

	guesses and estimates		76
		labeling	76
	importance of stating		120
	reasons for		74-76, 120
		catalog and purchased parts	75-76
		incomplete drawings	74-75
		missing information	74-76
		plus/minus	74-76
		relying on manufacturing process tolerances	74-76
	role of		74-76
Calculating part tolerances from a final assembly tolerance			367-372
	adjusted RSS part allocation formula		370-372
	in complex assemblies		367
	iteration		367-369
		spreadsheets and	369
	RSS part allocation formula		371-372
	what-if tolerancing		367-369
Central limit theorem			30-31
	Gaussian distribution and		31, 106
Chain of dimensions and tolerances			53, 54, 57, 61, 63-64, 67, 78-104, 287-289
	definition of		53, 104
	moving from one interface to another in		99-104
	reason for term		104
Complete Dimensioning and Tolerancing			4, 6, 8-14
Converting plus/minus dimensions and tolerances into equal bilateral format			33-37, 37-41, 65
	limit dimensions		33-34
	and mean shift		37-41
	unequal bilateral		34-35
	unilateral negative		36-37
	unilateral positive		35-36
Coordinate measuring machine (CMM)			6, 386
Coordinates and coordinate systems			5, 137
	Cartesian		5
	and datum reference frames		137
	and dimensions		5
	polar		5
	rectangular		5
Datum feature shift			48, 100-103, 147, 151, 180-187, 264, 270-286, 288, 293-296
	calculations for		182-186
	and datum feature simulation rules		181, 182-187

		datum features of size simulated at MMC size	182-184
		datum features of size simulated at MMC virtual condition size	184-187
	and datum features of size		182
	definition of		180
	direction of		288, 293-296
	geometric tolerances and		181
	material condition modifiers and		181, 268, 270-271
	rules for		190-192
	separate requirements and		187, 192-195
	similarity to assembly shift		183
	simultaneous requirements and		147, 151, 187-192
	sources of		180-181
Datum reference frames			107, 137, 139-140, 146-149, 160, 171-172, 394
	coordinate systems defined by		107, 137
	functional		137, 171-172, 394
	more than one		137-138
Dimension			
	types of		
		angular (polar)	15-16
		basic	18, 100-103, 141-145
		chained	15-16
		diametral	15-16
		linear	15-16
		math-data based, model-based	6, 10-12, 18-20
		radial	15-16
		rectangular coordinate	15, 17-18
Dimensioning and tolerancing philosophy			4-6, 8-14, 17-18, 57, 137, 154, 158-159, 171-172, 194, 201, 204, 216, 225-231, 330, 394
	avoiding ambiguity		57, 216
	functional dimensioning and tolerancing		17-18, 57, 137, 154, 158-159, 171-172, 194, 201, 204, 216, 225-231, 330, 394
Dimensioning strategy	(see also Functional dimensioning and tolerancing)		17, 18, 57
	and arrangement of dimensions		18
	effect on Tolerance Stackups		17, 57
Direction of dimensions and tolerances in the tolerance stackup			58, 287-296, 302, 303-327
	rules for including		295-296
	tolerance stackup direction and		288, 295-296, 302
	in tolerance stackups solved as a combination of translational and rotational variation		293-296, 303-327
	in tolerance stackups solved as translational variation only		288-289, 293-296, 303-327
Drawings			
	history of		3-4

	limited dimension		6, 15
	math based, model based		6, 15, 267
Enclosure assembly			
	drawings		330-338
		assembly	330, 337
		cover	338
		enclosure: option 1	331
		enclosure: option 2	332
		enclosure: option 3	333
		ground plate: option 1	334
		ground plate: option 2	335
		ground plate: option 3	336
	tolerance stackup examples		
		cover fit along X axis	339-345
		cover fit along Y axis	342-349
		ground plate to enclosure: option 1	353-356
		ground plate to enclosure: option 2	356-360
		ground plate to enclosure: option 3	360-365
		screw head clearance	346-352
		screw thread depth	337-341
Feature			5, 18, 22, 102
	bounded		5
	characteristics of		22
		form	22, 23-24
		location	22, 24-25
		orientation	22, 24
		size	22-23
	complex		5, 102
		"blending" the surface of	6
		shape of	102
	definition of		5
	simple		5
Feature control frames			18, 146, 147, 148, 149, 159
Feature of size			5, 100-103
	rule #1 and		5
Fit classifications			389-391
	clearance fit		389, 390
	interference fit		389, 391
	transition fit		389, 390
Fixed fastener situation			383-388
	assembly process and		388
		assumptions	383, 384
	assembly shift and		388
	calculations		385, 387-388
	datum features and		386
	defined		373, 383
	examples of		383
	formula		384

		distribution of tolerances in variables	384, 385 384
	interrelationship between part tolerances		384, 386
	limitations of		388
	positional tolerance and		384-388
	projected tolerance zone and		384-386
	virtual condition and		388
Fixtures			53-54
	chain of dimensions and tolerances and		54
	tolerances of		54-55
Floating fastener situation			373-383
	assembly process and		378-383
		assumptions	378, 382
	assembly shift and		378-383
	calculations		375, 377-378
	datum features and		376
	defined		373-374
	effect of gravity and		379-380
	examples of		374
	formula		374, 375
		variables	374
	interrelationship between part tolerances		375-376
	limitations of		378
	positional tolerance and		374-378
	virtual condition and		376, 378
Form tolerances in tolerance stackups			285-286, 393-428
	assembly forces and		395, 402-412, 420-425
	datum feature form tolerances		394-395
	difference between inspection and assembly		394-402
	effect on tolerance stackup		395-412
		as rotational variation projected to a linear displacement	395, 402-412, 420-425
		as translational variation only	395-402, 412, 417-420
	examples of		
		as rotational variation projected to a linear displacement	402-412, 420-425
		as translational variation only	395-402, 417-420
	and idealization of the problem		393
		how to include form tolerances in the tolerance stackup	412, 414-425
		how to quantify the potential effect of the form tolerances	412, 425-427
		whether form tolerances should be included in the tolerance stackup	395, 412, 413

		whether variation allowed by form tolerances should be treated as translation or rotation	412, 413-414
	mating surfaces and		394-402
	mean shift and		417-424
	other sources of form error		428
	probability of occurrence		395, 401-402, 411-412, 425-427
	step-by-step instructions for including		417-425
Format, plus/minus tolerances			
	conversion of +/- into equal bilateral		33-37, 65
	conversion of GD&T into equal bilateral		138-139
		position	154, 178-180
		profile	139-145
	dimensional limits and		30
	effect on manufacturing process		29-31
	effect on target value		29-31
	equal bilateral		27
	examples of		28
	legal differences		29-31, 37
	limit dimensions		27
	rules for		28
		leading zeroes	28
		number of decimal places	28
		trailing zeroes	28
	SPC and		29-31
	unequal bilateral		27
	unilateral		27
Functional dimensioning and tolerancing			17-18, 57, 137, 154, 158-159, 171-172, 194, 201, 204, 216, 225-231, 330, 394
	justifications for		57
	tolerance stackups and		57
GD&T			5, 13-14, 16, 18-21, 22-25, 45, 48, 54, 74-75, 100-104, 137-200, 245-247, 264-266, 268-286
	basic dimensions		18, 100-103, 141-145
		measuring in CAD	142
	benefits of		4, 13-14, 17-21, 75, 107-108
	bonus tolerance		48, 102-103, 154, 158-159, 169, 171, 180, 227, 229-231, 264, 268, 270-286
		and material condition modifiers	154, 158-159, 169
	comparison with +/-		4, 13-14, 74, 75, 107-108, 138
	concentricity, limitations of		215
	converting +/- to positional tolerances		178, 201-207
		Pythagorean theorem	201-206
		right angle solution	205-206
	datum feature		100-103, 137, 353-365
		affect on tolerance stackups	100-103, 353-366
		complex	102
		feature of size	102-103

	planar	100-101
datum feature shift		48, 100-103, 180-188, 264, 270-286
	calculations for	182-186
	and datum feature simulation rules	181
	and datum features of size	182-183
	datum features of size simulated at MMC size	182-184
	datum features of size simulated at MMC virtual condition size	184-188
	definition of	180
	geometric tolerances and	181
	material condition modifiers and	181, 268, 270-271
	rules for	190-192
	separate requirements and	187, 192-195
	similarity to assembly shift	183
	simultaneous requirements and	147, 151, 188-192
	sources of	180-181
	tolerance stackup direction and	293-296
datum reference frames		137, 139-140, 146-149, 160
	coordinate systems defined by	107, 137
	functional	137, 171-172, 394
	more than one	137-138
feature control frames		18, 146, 147, 148, 149, 159-163, 189, 207
	projected tolerance zones in	207, 384-386
feature of size		5, 100-103
form tolerances		101, 285-286, 393-428
fundamental rules		54
interfaces in the tolerance stackup and		99-104, 137
	functional datum features	137, 171-172, 394
material condition modifiers		48, 69-71, 97, 153-154, 225-231, 268, 270-271
	alignment and	158-159
	bonus tolerance and	154, 158-159, 169, 227, 229-231, 264, 268, 270-286
	effect on tolerance zones	154, 158-159
	LMC	48, 69-71, 97, 153-154, 157, 158
	MMC	48, 153-154, 156, 158-159
	part cost and	159
	RFS	154, 155, 158
	symbols for	154, 226
	tolerance charts	155-157
	variation and	158-159
orientation tolerances		101, 102, 104, 282-285
positional tolerances		102-103, 153-180
	assembly shift, misalignment and	154, 158-165
	bonus tolerance and	48, 102-103, 169, 171, 180
	circumscribing a cylindrical zone for converting +/- to position	178, 201-207

	composite position	104, 160-173
	converting +/- to positional tolerances	178, 201-207
	converting to equal bilateral +/-	154, 178-180
	datum reference frames and	160, 267, 268, 270-286
	features of size and	153-154
	in fixed- and floating-fastener formulas	161-164, 167, 168, 373-388
	including upper and lower segment tolerances in the tolerance stackup	160-173
	inner and outer boundaries and	155
	material condition modifiers and	153-154
	projected tolerance zones	207-213, 384-386
	reporting in a tolerance stackup report	160, 178-180, 275-283
	simultaneous requirements and	161, 167
	tolerance zone	153-160, 201-207
	virtual and resultant condition and	156-157
	profile tolerances	100-101, 139-153, 271-277
	benefits of	139-140
	complex surfaces	141-142
	composite profile	101, 146-153
	converting to equal bilateral +/-	140-145
	datum reference frames and	139-140
	equal bilateral	140-142
	including upper and lower segment tolerances in the tolerance stackup	145-153
	planar surfaces	141
	reporting in a tolerance stackup report	141, 143, 145, 147, 149-152, 271-277
	similarities to +/-	139-140
	simultaneous requirements and	147, 151
	tolerance zone	139-147
	unequal bilateral	142-144
	unilateral	144-145
	universal applicability	140
	projected tolerance zones	207-213, 384-386
	automated tools for calculating	208
	and CMMs	208, 386
	effect inside and outside the part	210
	examples of	209-210
	in fixed fastener calculations	213, 384-386
	formulas to calculate equivalent tolerance when projected tolerance is not specified	211-213
	methods of specifying	207-209
	reasons for	207-208
	reluctance of companies to use	208
	in tolerance stackups	208
	rule #1	5
	runout tolerances	286
	separate requirements	187, 192-195

		compared with simultaneous requirements	192, 195-199
		and datum feature shift	
		and datum reference frames	192
		examples of	195-199
		and feature control frames	192
		and functional dimensioning and tolerancing	194
		and inspection	192
		rules for including datum feature shift in the tolerance stackup	192
	simultaneous requirements		147, 151, 188-192
		and the chain of dimensions and tolerances	190-192
		and datum feature shift	187, 189-192
		and datum reference frames	188-192
		default condition per ASME Y14.5M-1994	187-188
		examples of	195-199
		and feature control frames	188
		and inspection	188-192
		overriding	187, 193
		and patterns	189-190
		rules for including datum feature shift in the tolerance stackup	190-192
	use of +/- on drawings based on		138
Geometric characteristic symbols			21
History			3-4
	of design & manufacturing practices		3-4
	of engineering drawings		3-4
	of tolerance analysis		1-4
Interchangeability			2
Justification for GD&T			4, 137-138
Loop (see Chain of dimensions and tolerances)			
Manufacturing processes			7-8, 43-48
Material condition modifiers			48, 69-71, 97, 153-154, 155, 156, 158-159, 169, 225-231
	bonus tolerance and		154, 158-159, 169, 227, 229-231
	choosing the correct modifier		225, 227-231
		alignment	229-230
		combination of factors	230-231
		edge distance or wall thickness	229
		fit or clearance	228
		selection criteria	227-231
	difference between the material condition modifiers		226-227
	effect on datum feature shift		225

	effect on tolerance stackup		225
	effect on tolerance zone		153-154
	entering into the tolerance stackup report		225
	LMC		48, 69-71, 97, 153-154, 157, 158, 225, 227
		definition of	227
		effect on tolerance zones	154, 158-159
		and internal and external features	227
	MMC		48, 153-154, 156, 158-159, 226-227
		definition of	226-227
		effect on tolerance zones	154, 158-159
		and internal and external features	226-227
	part cost and		159
	positional tolerance and		153-154
	RFS		154, 155, 158, 225-226
		ANSI Y14.5M-1982	226
		definition of	226
		effect on tolerance zones	154, 158-159
		as a subset of MMC and LMC	227
	symbols for		154, 226
	tolerance charts		155-157
	variation and		158-159
Mean			39-40
	definition of		40
Mean shift			37-41, 150, 417-424
	calculation of		38-41
		limit dimensions	38
		unequal bilateral tolerances	38
		unilateral tolerances	38-39
	definition of		37
	effect on Tolerance Stackup		38-40
		form tolerances and	417-424
		with and without dimensions	38-39
	form and orientation tolerances and		150, 417-424
	and manufacturing		40
	sign and direction of		39
Mean, Arithmetic			
	definition of		40
Moving from one part to another in a tolerance stackup			99-104
	complex-curved interfaces		102
	disclaimer		104
	feature-of-size interface		
		for +/- dimensions and tolerances	102
		for GD&T - if it is a referenced datum feature	102-103
		for GD&T - if it is not a referenced datum feature	103-104

	guidelines for		99-104
	planar interface		
		for +/- dimensions and tolerances	100
		for GD&T - if it is a referenced datum feature	100-101
		for GD&T - if it is not a referenced datum feature	101
Nominal			4, 6, 15, 16, 27, 29, 37-41, 44, 102, 105, 107, 139
	dimension value and		4, 15, 16, 27, 29
	manufacturing nominal		30-31
	math-data/model-data and		6, 12, 44
	mean shift of		37-41
	statistical tolerance stackups and		105, 107
Orientation tolerances in tolerance stackups			393, 395
	(see also form tolerances in tolerance stackups)		393-428
Probability			30, 105-108
Rule #1			5
Separate requirements			187, 192-195
	compared with simultaneous requirements and datum feature shift		192, 195-199
	and datum reference frames		192
	examples of		195-199
	and feature control frames		192
	and functional dimensioning and tolerancing		194
	and inspection		192
	rules for including datum feature shift in the tolerance stackup		192
Simultaneous requirements			147, 151, 187-192
	chain of dimensions and tolerances and		190-192
	and datum feature shift		187, 189-192
	and datum reference frames		188-192
	default condition per ASME Y14.5M-1994		187, 188
	examples of		195-199
	and feature control frames		188
	and inspection		188-192
	overriding		193
	and patterns		189-190
	rules for including datum feature shift in the tolerance stackup		190-192
Statistical Process Control (SPC)			13, 29-31, 105-107
Statistical tolerance stackup			99, 105-136
	adjusted statistical tolerance stackup		107-109, 120-136
	appropriateness of		105-106
		number of dimensions and tolerances and	105-106

	assembly tolerance and		108
	chain of dimensions and tolerances in		110-111, 120-136
	comparison with worst-case result		120-136
	conditional assumptions		99, 106
	examples using Advanced Dimensional Management method		119, 149, 150, 151, 152, 169, 170, 172, 173, 176, 196, 197, 198, 237-240, 241, 242, 244, 252, 253, 261, 290, 291, 308, 311, 319, 322, 329-366
	examples using GD&T - simplified		
		complex bolted assembly	168-178
	examples using plus/minus - simplified		120-136
		assembly with effect of gravity	127-129
		complex bolted assembly	133-136
		complex welded assembly	130-133
		simple assembly	125-127
		single part	121-125
	manufacturing process controls and Monte-Carlo		106 107
	probability and results		105-108 105-136
	root-sum-square (RSS) and		107-108, 114-117, 120-136
		definition of	107
		formula for	107
		process related assumptions and standards deviations (σ) and	108 108
	spreadsheets and		116-120
		benefits of	116-119
		preformatted tolerance stackup report format	116-119, 120
	statistical process control (SPC) and		106-109
		C_p & C_{pk}	107
	step-by-step procedure		109-118
		adjusted statistical result	116, 118
		converting the dimensions and tolerances into equal bilateral format	112-113
		determining the nominal distance being studied	115, 117
		determining the positive and negative directions	110-113
		determining the upper and lower limits	116-118
		entering data into the tolerance stackup report form	100-104, 114-118
		labeling positive and negative direction dimensions	110-113
		labeling the distance being studied	109-110
		root-sum-square (RSS) and	114-117

	tolerance distribution and		106
Tolerance			
	conversion of +/-		33-37, 65
	conversion of GD&T		
		position	154, 178-180
		profile	140-145
	definition of		7
	effects of not specifying		8-14
	format of		27-30
		effect on manufacturing process	29-31
		effect on target value	29-31
		equal bilateral	27
		examples of	28
		legal differences	29-31
		limit dimensions	27
		rules for	28
		SPC and	29-31
		unequal bilateral	27
		unilateral	27
	importance of		4, 6
	range		39
	types of		20-25
		+/-	16-20
		angular	20
		form	22, 24
		general note - default	20
		geometric	14, 16-21
		local	20
		location	22, 24-25
		orientation	22, 24
		size	22-23
		statistical	105-136
		title block - default	20
		worst-case	58
Tolerance analysis			2, 51-60
	assumptions in		74-78, 99, 120
	computer modeled		59
	of cumulative variation		51-52
	definition of		51
	design complexity and		2
	at different stages in a project		
		before and after production	52
	importance of specifications in		51
	of individual tolerances		51
	manually modeled		58
	methods and types of		58-59
	reasons for		51-53, 55-56, 58
		clearance and interference	53

	statistical		58, 105-136
		root-sum-square (RSS)	59, 107
	steps of performing		51-52
	three-dimensional		59, 62, 107
		Monte-Carlo	107
	worst-case (arithmetic)		58
Tolerance stackup			
	Advanced Dimensional Management method		119, 149, 150, 151, 152, 169, 170, 172, 173, 176, 196, 197, 198, 237-240, 241, 242, 244, 252, 253, 261, 290, 291, 308, 311, 319, 322, 329-366
	assumptions in		74-78, 107, 99, 120
	calculating part tolerances from a final assembly tolerance		367-372
		adjusted RSS part allocation formula	370-372
		RSS part allocation formula	371-372
	chain of dimensions and tolerances in		53, 54, 57, 61, 63, 99-104, 165
		including dimensions and tolerances in	56, 58, 287-288, 293-296
	and decision making		53, 303
	at different stages in a project		
		before and after production	52
	definition of		51, 53
	determining which dimensions and tolerances to include		56, 58, 287-288, 293-296, 303
	diametral and radial tolerance stackups		215-224
		calculating coaxiality error / misalignment in	216, 218-224
		coaxiality versus concentricity	215
		controlling coaxiality with GD&T	216
		datum feature shift and	219
		examples of	217-224
		formula with variables	218-218
		material condition modifiers and	216-224
	direction of		58, 287-289, 293-296
		dimensions, tolerances and other variables	293-296
		linear one-dimensional stackups	58, 77
	effect of assembly process on		57-58, 108, 233-234, 353-366
	effect of dimensioning and tolerancing schemes on		56-57, 236, 353-365
	effect of part and assembly geometry on		56, 287-327, 367-368
		effect of changing part and assembly geometry	367-368
		locating features closer together	316-327
		locating features farther apart	305-316
		rotation of parts in an assembly	303-327
	elimination of ambiguity in		107-108
	fixed fastener		383-388
	and fixtures		53-55

	floating fastener		373-383
	form tolerances in		285-286, 393-428
	importance of GD&T in		107-108
	iteration in		367-369
	moving from one part to another in		99-104
	purpose of		51-52, 55-56, 58, 303
	rotation of parts within a linear tolerance stackup		293, 303-327
		affect on the tolerance stackup	305
		comparisons of translational variation versus rotational variation in a linear tolerance stackup	293, 303-327
		importance of	305
		locating features closer together	316-327
		locating features farther apart	305-316
		reporting in a tolerance stackup report	309, 311, 316, 322, 323, 327
	separate requirements and		192-195, 196-199
	simultaneous requirements and		187-192, 195-199
	statistical		58, 105-136
		examples of	120-136
		root-sum-square (RSS)	59, 107
	steps of, general		55
	subjects of a		51-52, 303
		clearance and interference	53
		examples of	52
	as a subset of tolerance analysis		52
	units		302-303
		determining which units to report in a tolerance stackup	303
	without dimensions		142
	worst-case (arithmetic)		58, 61-104
		examples of	58, 61-104
Tolerance stackup report			62, 66-67, 80, 83, 86, 89, 93, 97, 100-104, 116-120, 169, 249-286, 329-366
	Advanced Dimensional Management tolerance stackup report form		119, 253, 261, 329-365
	as a communication tool		250-251
	consistency and		117-118, 250-251
	data entry in		62, 100-104, 111-118
	data fields in		120, 251-260
	decision making and		249-250
	examples of		
		Advanced Dimensional Management method	119, 150, 152, 170, 173, 196, 197, 241, 244, 252, 253, 261, 291, 308, 311, 319, 322, 329-366, 398, 419, 421, 424, 426
		simplified	67, 80, 83, 86, 89, 93, 97, 117, 118, 122, 124, 126, 129, 131, 135, 177

	format of		251
	general guidelines for description, part number and revision information		260-262
	guidelines for entering dimension and tolerance data		262-268
		+/- dimensions and tolerances	262-264
		basic dimensions	266-268
		bonus tolerance	264, 268, 270-286
		datum feature shift	264, 270-286
		datum reference frames	160, 267, 268, 270-286
		form tolerances	285-286, 393-428
		GD&T	264-266, 268-286
		material condition modifiers	268, 270-271
		orientation tolerances	282-285
		positional tolerances	160, 178-180, 275-283
		profile tolerances	141, 143, 145, 147, 149-152, 271-277
		runout tolerances	286
	importance of preformatted tolerance stackup report format		116-120, 250-251
	purpose of		249-251
	reasons for		249-250
	simplified examples for +/-		80, 83, 86, 89, 93, 97
	step-by-step instructions for completing a simplified tolerance stackup form		65-67
	step-by-step instructions for filling out the Advanced Dimensional Management tolerance stackup report form		251-260
		assumptions block	260
		data entry block	254-258
		notes block	259-260
		results block	258-259
		suggested action block	260
		tracking and title block data	253-254
	step-by-step simplified introduction for worst-case +/-		66-67
	tolerance stackup report form		116-120, 249-286
Tolerance stackup sketch			62-67, 80, 83, 86, 88, 92, 96, 169, 233-247, 287-288
	annotation in		238-247
		assembly shift	238-240, 243, 245, 246
		contributing dimensions and tolerances	238-239, 243, 246
		datum feature shift	238-240, 246
		dimension direction labels	238-240, 243, 246
		identification of the distance or gap being studied	238-239, 243, 245
		item numbers	238-240, 245, 246-247

		part identification	238-239, 243, 245
		title and reference information	238-239, 245, 247
		tolerance stackup direction	238-240, 243, 245-246
	chain of dimensions and tolerances and as a communication tool		233, 236, 240, 243, 246-247
	content of		233, 247
	correlating with the tolerance stackup report		236-237
	dimensioning and tolerancing schemes and examples of		239, 241-243, 245, 247
		Advanced Dimensional Management method	236
		for drawings based on +/-	119, 149, 151, 169, 172, 176, 198, 237-240, 242, 290, 329-366, 397, 418, 420, 423, 425
		for drawings based on GD&T	240
		simplified	242
	form tolerances in		67, 80, 83, 86, 88, 92, 96, 117, 118, 122, 124, 126, 129, 131, 135
	importance of		393-428
	part and assembly geometry in		233-236, 287-288
		clarity and	237-239
		scale of	238-239
		sources of	238
	purpose of		236-237, 247
	reason for		233, 234-236, 247, 287-288
	required information		233-236
		assembly drawings	233, 236
		catalog and purchased item drawings	233, 235
		manufactured component drawings	233-234
		part and assembly model(s)	233
	simplified examples for +/-		80, 83, 86, 88, 92, 96
	step-by-step directions for completing		243-247
		for drawings based on +/-	243-245
		for drawings based on GD&T	245-247
		simplified	61-67
	step-by-step simplified introduction for worst-case +/-		62-67
	timing of		233
	visualization of the problem and		233, 236, 247, 287-288
Trigonometry	converting +/- to positional tolerance zone		99-100, 141-142, 201, 287-327, 343-345, 347-349
		Pythagorean theorem	201-207
		right angle solution	201-206
	converting angular dimensions and tolerances into linear units		205-206
		+/- example	296-302
			297-299

		GD&T example	300-302
	like triangles		304-305, 407-408, 422, 423
	projection into the tolerance stackup direction		99-100, 141-142, 287-302
	rotation of parts within a linear tolerance stackup		303-327
	tolerance stackup units and		302-303
		linear units	302
		polar units	302
Units			302-303
	determining which units to report in a tolerance stackup		303
Variation			43-49, 53-54, 58, 108, 233-234, 287, 293
	of actual parts versus models		44
	defining allowable		43-44
	definition of		43
	from a design point of view		43
	from a manufacturing point of view		43
	from a measurement point of view		43
	from a tolerance analysis point of view		44
	prediction of		
		by a tolerance stackup	53, 58
	reducing predicted		53-54
		fixturing	53-54
	sources of		45-49
		ambient conditions	46-47
		assembly process	48-49, 108, 233-234
		difference in process	47
		difference in processing equipment	47
		inspection process	48
		manufacturing process capability	45
		operator error and bias	46
		poor maintenance	47-48
		tool wear	46
		variations in material	46
	tolerances and		44
Worst-case tolerance stackup			61-104
	chain of dimensions and tolerances in conditional assumptions		61, 63-64, 67, 78-104
			61, 77-78, 99
	examples using Advanced Dimensional Management method		119, 149, 150, 151, 152, 169, 170, 172, 173, 176, 196, 197, 198, 237-240, 241, 242, 244, 252, 253, 261, 290, 291, 308, 311, 319, 322, 329-366
	examples using GD&T - simplified		
		complex bolted assembly	168-178
	examples using plus/minus - simplified		78-99
		assembly with effect of gravity	87-90
		complex bolted assembly	93-99
		complex welded assembly	90-93

		simple assembly	84-87
		single part	79-84
	results		61
	step-by-step procedure		61-68
		converting the dimensions and tolerances into equal bilateral format	33-37, 65
		determining the nominal distance being studied	65-66
		determining the positive and negative directions	62-64
		determining the upper and lower limits	66, 67
		entering data into the tolerance stackup report form	65, 100-104
		labeling positive and negative direction dimensions	62-65, 68
		labeling the distance being studied	61-62
		summation of values	65